SAFETY MEETING 2021







and the second second



AGENDA

Welcome!
Tail swing Accidents G.O.A.L

 a. Cost to the Company
 b. Cost to the Driver

Cargo Inspection

 a. Cost to the company
 b. Cost to the driver

Understanding The SMS System

a. DOT Violations

5. Pedigree Tablet

a. Where to find Documents

b. Log Certification

c. Proper DVIR Reporting




ц?






凸













Deck 5 flippers must be flipped over in the closed position

Deck 9 must be pulled all the way into the rear bumper

This is a DOT regulation























	0		TREADO COLLISI LIFE TIME Guarantee on all w as you own you 121 PARKERS MILL treadocollision@gmail.com, S Phone: (606) 6 FAX: (606) 67	orkmans r vehicle ROAD, Er OMERSE 77-1900 7-1414	hip! As long nail:	P	orkfile ID: artsShare:		6qMmJ6
			Estima	te					
RO N	umbe	r:				Estim		Kenneth A	chløv
Custom	er:		Insurance: Adjus					9/10/202	Second and
young,	kyle		Phone			Creat	e Date.	1 10/202	•
			Claim						
			Loss	2010/20					
(606) (69-927	2	Dedu	ctible:					
2018 0	HEV Sile	verado 1500 LT1 Cre	w Cab 143.5" WB 4WD 4D SHORT 8-5.3L Fk	x Fuel Dire	ct Injection				
VIN:		UKREC8JG631580	Interior Color:		Mileage In:		Vehicle O	lut:	
License		UKREC63G031300	Exterior Color:		Mileage Out:				
State:	5.		Production Date:		Condition:		Job #:		
State:			110000000						
Line	Ver	Operation	Description	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		FRONT BUMPER				0.07	Mash	
2	E01	Remove/Replace	Add for park sensor			OEM		Mech	0.9T
3	E01	Remove/Replace	RT Filler panel	1	58.88T	OEM	0.21	Body	0.91 0.4T
4	E01		Add for Three Stage					P-d-	0.41
5	E01	Remove/Replace	Add for fog lamps			OEM		Body	0.9T
6	E01	Remove/Replace	LT Filler panel	1	58.88T	OEM	0.21	Body	1.1T
7	E01		Add for Three Stage						1.11
8	E01	Refinish	Tint Color				2.07	Darth	1.51
9	E01	Overhaul	O/H bumper assy			OEM		Body	
10	E01	Remove/Replace	Bumper filler w/o skid plate w/tow hoo		476.07T	OEM		Body	
11	E01	Remove/Replace	Air deflector	1	104.30T	OEM		Body	
12	E01	Remove/Replace	Skid plate	1	193.58T	OEM		Body	
13	E01	Remove/Replace	Front bumper w/o park assist, w/o fog lamps chrome	1	799.95T	OEM		Body	
14	E01	Remove/Install	Harness w/o fog lamps w/o park assis	t			0.0T	Body	
15	E01		GRILLE						
16	E01	Remove/Replace	Grille LTZ	1	886.88T	OEM		Body	
17	E01	Remove/Replace	Dis/reassmble to refn					Body	
18	E01	Remove/Replace	Emblem	1	135.95T	OEM	0.01	Body	-
		Estimate Total	ls Discount \$ Ma	rkup \$	Rate \$	г	otal Hours		Total \$
									2,714.49
		Parts			50.00				285.00









			4901 E	Collision 'Your Collision Imore Rd, MEN Phone: (901) FAX: (901) 2	Specialis MPHIS, T 266-114	N 38128 1		Vorkfile ID: PartsShare:		e3b94828 6fy53m
				Estima	ate					
RO N	lumbe	er: 13831								
Custon			Insurance:		ister:		Estim		Wayne S	
Gosset	t Motor	s		Phor	ne:		Create	e Date:	5/7/2021	
	Covingto			Clair		MD029862				
-	his, TN				Date:					
(901) :	388-896	39		Ded	uctible:					
2021 /	NDI Q	8 55 Prestige Quattro	TFSI 4D UTV 6-3.0L Turb	ocharged Hybrid G	Gasoline Dir	rect Injection bla	sck			
VIN:	W	1FVAF17MD029862	Interior Color:	black		Mileage In:	13	Vehicle (Dut:	
License	e:		Exterior Color:	black		Mileage Out:				
State:	TN		Production Date:	2/2021		Condition:		Job #:		
Line	Ver	Operation	Descr	iption	Qty	Extended Price \$	Part Type	Labor	Туре	Paint
1	E01		QUARTER PANEL							
2	E01	Remove/Replace	RT Wheel opng midg 01/21/2019	Q8, SQ8 fm	1	305.00	OEM	0.2	Body	0.3
3	E01		Add for Clear Coat							0.1
4	E01	Remove/Install	LT Wheel opng midg	08, S08 fm				0.2	Body	
			01/21/2019	40, 540 m						
5	E01									
5 6	E01	Remove/Install	01/21/2019					0.3	Body	
6 7	E01 E01		01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co	de: 8SP					Body Body	
6 7 8	E01 E01 E01	Remove/Install Remove/Install	01/21/2019 REAR LAMPS RT Tail lamp assy co	de: 8SP				0.3	Body	
6 7 8 9	E01 E01 E01 E01	Remove/Install Remove/Install Overhaul	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy	de: 8SP de: 8SP			OEM	0.3 4.2	Body	
6 7 8 9 10	E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side	de: 8SP de: 8SP			ОЕМ	0.3 4.2 0.0	Body Body Body	
6 7 8 9 10 11	E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side Park sensor center	de: 8SP Je: 8SP w/surround view			ОЕМ	0.3 4.2 0.0 0.0	Body Body Body Body	
6 7 8 9 10 11 12	E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install Remove/Install	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side Park sensor center LT Park sensor side	de: 8SP Je: 8SP w/surround view				0.3 4.2 0.0 0.0 0.0	Body Body Body Body Body	
6 7 8 9 10 11 12 13	E01 E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side Park sensor center LT Park sensor side Upper cover	de: 8SP Je: 8SP w/surround view	1	850.00	OEM	0.3 4.2 0.0 0.0 0.0	Body Body Body Body	2.5
6 7 8 9 10 11 12 13 14	E01 E01 E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install Remove/Install Remove/Replace	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side Park sensor center LT Park sensor side of Upper cover Add for Clear Coat	de: 8SP de: 8SP w/surround view w/surround view	1	850.00		0.3 4.2 0.0 0.0 0.0 0.0	Body Body Body Body Body Body	1.0
6 7 8 9 10 11 12 13 14 15	E01 E01 E01 E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install Remove/Install	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor sider Park sensor center LT Park sensor sider Upper cover Add for Clear Coat Lower cover w/sensor	de: 8SP de: 8SP w/surround view w/surround view	1	850.00		0.3 4.2 0.0 0.0 0.0 0.0	Body Body Body Body Body	1.0 1.8
6 7 8 9 10 11 12 13 14 15 16	E01 E01 E01 E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install Remove/Install Remove/Replace Repair	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side Park sensor center LT Park sensor side Upper cover Add for Olear Coat Lower cover w/senso Add for Clear Coat	de: 8SP de: 8SP w/surround view w/surround view	-		OEM	0.3 4.2 0.0 0.0 0.0 0.0	Body Body Body Body Body Body	1.0
6 7 8 9 10 11 12 13 14 15 16 17	E01 E01 E01 E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install Remove/Replace Repair Remove/Replace	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side to Park sensor center LT Park sensor side to Upper cover Add for Clear Coat Lower cover w/sensor Add for Clear Coat Hardware kit	de: 8SP de: 8SP w/surround view w/surround view or side protection	1	111.67	OEM	0.3 4.2 0.0 0.0 0.0 0.0 3.0	Body Body Body Body Body Body	1.0 1.8
6 7 8 9 10 11 12 13 14 15 16	E01 E01 E01 E01 E01 E01 E01 E01 E01 E01	Remove/Install Remove/Install Overhaul Remove/Install Remove/Install Remove/Install Remove/Replace Repair	01/21/2019 REAR LAMPS RT Tail lamp assy co LT Tail lamp assy co REAR BUMPER O/H bumper assy RT Park sensor side Park sensor center LT Park sensor side Upper cover Add for Olear Coat Lower cover w/senso Add for Clear Coat	de: 8SP de: 8SP w/surround view w/surround view or side protection t	-		OEM	0.3 4.2 0.0 0.0 0.0 0.0 3.0	Body Body Body Body Body Body	1.0 1.8

Estimate Totals	Discount \$	Markup \$	Rate \$	Total Hours	Total \$
Parts					1,276.67
Sublet/Miscellaneous					5.00

T – Taxable Item, RPD – Related Prior Damage, AA – Appearance Allowance, UPD – Unrelated Prior Damage, PDR – Paintisss Dert. Repair, A/M – Aftermarket, Redr – Redrivored, Renan – Remanufactured, CEM – New Chiginal Equipment Manufacturer, Record, RECOND – Recorditioned, LNQ – Like Kind Quality or Used, Diag – Diagnostic, Bec – Bectrical, Mech – Mechanical, Ref – Refrints, Struc – Structural

5/10/2021 9:27:20 AM







PROPER INSPECTIONS

REDUCE THE AMOUNT PAID OUT IN CLAIMS BY THE COMPANY



Paid Claims

	YTD PAID Damage Claims thru 09/24/2021								
	Owner Oper	ators	Proficient Core	Drivers	PROFleet D	rivers	ALL DRIVE	RS	
Total Claim Count	22	0.15%	73	0.19%	69	0.32%	164	0.22%	
Missed on Inspection or didn't have verified	2	0.01%	12	0.03%	21	0.10%	35	0.05%	
Total Paid Claims YTD 2021	\$37,080.	00	\$110,065	.64	\$58,085.	98	\$205,231	.62	
2021 YTD Car Count	14780		38288		21793		74861		
			2(020 PAID Damag	e Claims				
Total Claim Count	22	0.12%	233	0.31%	80	0.35%	335	0.29%	
Missed on Inspection or didn't have verified	2	0.01%	40	0.05%	20	0.09%	62	0.05%	
Total Paid Claims 2020	\$40,276.	78	\$288,274	.70	\$75,212.	80	\$403,764	.28	
2020 Car Count	18050		74761		23062		115873		


\$146,000 has been awarded in Driver Bonus programs in just the past 8 months. Staying Damage Free, Accident Free, and Safety conscious provides opportunities to increase your annual income.


Missed On Inspection

The following pictures include claims that have been paid because the damages were missed on inspection

These claims are 100% preventable







ACCIDENTS

E E 745	Coverage	Purpose of Coverage	Cost to Proficient*
	Physical Damage	Pays for damage to equipment owned by Proficient	\$90,228.20
	Motor Truck Cargo	Pays for damage to cargo hauled under Proficient's BOL	\$30,000.00
	Auto Liability	Pays for 3rd party property damage and injuries due to MVC	\$90,049.33
			\$210,277.53
日本の	*total out-of-pocket dollar	s in the current policy period	



SMS SYSTEM

THE SYSTEM AND HOW IT WORKS







BASIC Status (Motor Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICs)

Based on a 24-month record ending August 27, 2021

How does SMS relate to crashes?





Select a BASIC icon above to get details, or view your Complete SMS Profile.

BASIC: Unsafe Driving

More Info

MEASURE

On-Road Performance

Measure: 2.86 ?

Safety Event Group: 22-57 driver inspections with Unsafe Driving Violations


Investigation Results

No Acute/Critical Violations Discovered


CARRIER MEASURE OVER TIME

This graph displays a carrier's measure based on 24 months of on-road performance. Zero indicates the best performance. To see how the measure is calculated <u>click here</u>. To see how the measure relates to percentile <u>click here</u>. <u>Expand</u> for more information.

-7



	CARRIER MEASURE OVER	TIME INSPEC	CTION RESULTS	
- VIOLATION SUMMARY			Unsafe Driving Violatio	ons: 38
Violations	Description	# Violations	# OOS Violations	Violation Severity Weight
392.2C	Failure to obey traffic control device	8	0	5
392.16	Failing to use seat belt while operating a CMV	6	0	7
392.2-SLLS3	State/Local Laws - Speeding 11-14 miles per hour over the speed limit.	5	0	7
392.82(a)1	Using a hand-held mobile telephone while operating a CMV	4	0	10
392.2-SLLS2	State/Local Laws - Speeding 6-10 miles per hour over the speed limit.	3	0	4
392.2FC	Following too close	3	0	5
392.2LV	Lane Restriction violation	3	0	3
392.2-INAT	Inattentive Driving	2	0	5
392.2-SLLSWZ	State/Local Laws - Speeding work/construction zone.	2	0	10
392.2-ML	Failure to Maintain Lane	1	0	5
392.2-SLLS4	State/Local Laws - Speeding 15 or more miles per hour over the speed limit.	1	0	10






CARRIER MEASURE OVER TIME

INSPECTION RESULTS

- VIOLATION SUMMA	RY		HOS Compliance Violations: 17				
Violations	Description	# Violations	# 00S Violations	Violation Severity Weight			
395.22H4	Driver failed to maintain supply of blank drivers records of duty status graph-grids	5	0	1			
395.22G	Portable ELD not mounted in a fixed position and visible to driver	2	0	1			
395.15(f)	Onboard recording device failure: Driver failed to reconstruct info	1	0	5			
395.20B	The ELDs display screen cannot be viewed outside of the commercial motor vehicle.	1	0	:5			
395.22H1	Driver failing to maintain ELD user's manual	1	0	1			
395.22H3	Driver failed to maintain instruction sheet for ELD malfunction reporting requirements	1	0	1			
395.24C2III	Driver failed to manually add shipping document number	1	0	1			
395.30B1	Driver failed to certify the accuracy of the information gathered by the ELD	1	0	1			
395.3A2-PROP	Driving beyond 14 hour duty period (Property carrying vehicle)	1	0	7			
395.3A3-PROP	Driving beyond 11 hour driving limit. (Property Carrying Vehicle)	1	0	7			
395.3A3-PROPN	Driving beyond 11 hour driving limit in a 14 hour period. (Property carrying vehicle) - Nominal Violation	1	0	1			
395.8F01	Drivers record of duty status not current	1	0	5			
+ INSPECTION HISTO	RY		Driver Inspections: 35	5			
+ INVESTIGATION RE	+ INVESTIGATION RESULTS			HOS Compliance Acute/Critical Violations: 0			



CARRIER MEASURE OVER TIME



CARRIER MEASURE OVER TIME

INSPECTION RESULTS

- VIOLATION SUMM	IARY		Driver Fitness Violatio	ens: 2
Violations	Description	# Violations	# OOS Violations	Violation Severity Weight
383.23(a)(2)	Operating a CMV without a CDL	1	1	8
391.41(a)(1)	Operating a property-carrying vehicle without possessing a valid medical certificate - no previous history.	1	0	1
+ INSPECTION HIST	ORY		Driver Inspections: 35	5
+ INVESTIGATION R	ESULTS		Driver Fitness Acute/0	Critical Violations: 0



THANK YOU!

WITHOUT YOU, THERE WOULD BE NO US...

